
## PROCESSING COPY

		sevelation of which in an			
					2
USSR (Kr	asnodarskiy Kra	ıy)	REPORT		
Reconstr	uction Work at	Sochi Airfield	DATE DISTR.	28 February 1	-957
R. J.	y Moder Set	; Extention of ! Your	NO. PAGES	1	
Junusy	, reliv Contral	somer.		RD	
		112	REFERENCES		25)
<b>2</b> .				*	
SOURC	E EVALUATIONS AR	E DEFINITIVE. APPR	AISAL OF CONTEN	T IS TENTATIVE.	
		one-page	e report, with	attached sketch,	1056
containing i at Sochi air		reconstruction v	work which was	underway on 4 June	± <u>1</u> 956 °
According to	the report +1-	e single mumo-	r of the field	was being extended	1
at both ends	to make possib	ole the landing	of jet fighter	rs. A new control was located in one	7
tower was al corner of th		. A TUKE		100aueu In one	
	Comment: This	report presuma	bly refers to	Sochi airfield	2
located at Nairfield in	43-36, E 39-44 October 1955 wa	+. [ as approximately	the 7 6,000 feet lo	e runway of this	25
					25X1
					25X1
		S-E-C-R-E-T			
		S-E-C-R-E-T		· .	25X1 25X1

Sanitized Copy Approved for Release 2010/02/23 : CIA-RDP80T00246A032700350001-0



	· · · · · · · · · · · · · · · · · · ·	
	U.S.S.R.	According to the second section of the second
	<u>Air</u>	Ś
	SOCHI AIRFIELD.	
	1. SOCHI ADLER airfield was, on June 4th, 1956, being	
	reconstructed in order to make possible the landing of jet	
	fighters.	
	2. Landings on this date were being made on a grass	
	strip on the South side of the airfield. The condition of	ر از از منس <sup>ت</sup> حدا
	this grass strip was very poor, and it would be quite unservice-	
	able in the event of heavy rain.	· · ·
	3. Work in progress on 4th June consisted of widening	
	and extending the existing single runway. Both ends of the	
	runway woro boing extended to some extent although it appeared	
	that natural obstaclos - foothills to the East and wooded and	
•	undulating ground to the West - would severely limit the	
	possible extension, especially to the East.	
	4. All extension work was being warried out in concrete,	
	apparently in hoxagonal blocks.	
	5. A now control towor was being constructed at the East	
	ond of the runway. There were no permanent hangars on the nirfield.	
	6. A TOKEN radar array was located in one corner of the	
	airfiold.	25X1
	and three photographs of the airfield are	
	attachod at Appondix 'A'. SECRET	
	-ttoobod of ADDUNULA ** *	

25X1

